

d = 1,40 - 3,60 mm**STAL ZWYKŁA LUB NIERDZEWNA**

HENNLICH Sp. z o.o. • ul. Wilsona 24A • 44-190 Knurów • tel. +48 (32) 42 06 711 • e-mail: sprezyny@hennlich.pl • www.hennlich.pl

d [mm]	D _e [mm]	D _i [mm]	L _o [mm]	Stal sprężynowa Symbol	Stal nierdzewna Symbol
1,40	9,8	7,0	1000	14/1	14/7
	12,6	9,8		14/2	14/8
	15,4	12,6		14/3	14/9
	18,2	15,4		14/4	14/10
	21,0	18,2		14/5	14/11
	23,8	21,0		14/6	14/12
1,60	11,2	8,0	1000	15/1	15/7
	14,4	11,2		15/2	15/8
	17,6	14,4		15/3	15/9
	20,8	17,6		15/4	15/10
	24,0	20,8		15/5	15/11
	27,2	24,0		15/6	15/12
1,80	12,6	9,0	1000	16/1	16/7
	16,2	12,6		16/2	16/8
	19,8	16,2		16/3	16/9
	23,4	19,8		16/4	16/10
	27,0	23,4		16/5	16/11
	30,6	27,0		16/6	16/12
2,00	13,0	9,0	1000	17/0	17/07
	14,0	10,0		17/1	17/7
	15,6	11,6		17/15	17/75
	18,0	14,0		17/2	17/8
	22,0	18,0		17/3	17/9
	26,0	22,0		17/4	17/10
	30,0	26,0		17/5	17/11
	34,0	30,0		17/6	17/12
2,25	15,8	11,3	1000	18/1	18/7
	20,3	15,8		18/2	18/8
	24,8	20,3		18/3	18/9
	29,4	24,8		18/4	18/10
	33,8	29,3		18/5	18/11
	38,3	33,8		18/6	18/12
2,50	15,5	10,5	1000	19/0	19/65
	17,5	12,5		19/1	19/7
	19,5	14,5		19/15	19/75
	22,5	17,5		19/2	19/8
	27,5	22,5		19/3	19/9
	32,5	27,5		19/4	19/10
	37,5	32,5		19/5	19/11
	42,5	37,5		19/6	19/12
2,80	19,6	14,0	1000	20/1	20/7
	25,2	19,6		20/2	20/8
	30,8	25,2		20/3	20/9
	36,4	30,8		20/4	20/10
	42,0	36,4		20/5	20/11
	47,6	42,0		20/6	20/12
3,20	22,4	16,0	1000	21/1	21/7
	28,8	22,4		21/2	21/8
	35,2	28,8		21/3	21/9
	41,6	35,2		21/4	21/10
	48,0	41,6		21/5	21/11
	54,4	48,0		21/6	21/12
3,60	25,2	18,0	1000	22/1	22/7
	32,4	25,2		22/2	22/8
	39,6	32,4		22/3	22/9
	46,8	39,6		22/4	22/10
	54,0	46,8		22/5	22/11
	61,2	54,0		22/6	22/12